2016 Charleston Area Stormwater Pond Management Conference

Budgeting and Funding for Stormwater Ponds


November 3, 2016

Peter B. Miller, RS, Principal




Introduction:


My first professional experience with Storm Water Ponds -




My first experience with Storm Water Ponds - 1982

1st Planned CIC in QA county! **New Chesapeake Bay Critical Area Regs! Rush to Open House! Hottest Day of the year! Pond Algae! Local Aquifer Dried Up! Angry Protesters at the Gate!**






Copyright 2016 Miller Dodson Assoc. Inc.







Budgeting and Funding for Stormwater Ponds

Challenge:

- Budget funding for "long-term", "large-ticket" expenditures.
- Spread funding equitably over time.

Replacement Reserve Study

- Established and accepted budget forecasting system.
- Based upon:
 - Replacement Costs
 - Remaining Useful Life
- Analyses required annual funding

Replacement Reserve Study

- Used successfully for 30+ years by:
 - Condos, HOAs Coops, Timeshares (CIC's)*
 - Country Clubs & Yacht Clubs*
 - Religious Institutions & Private Schools*
 - Municipal Governments
 - Commercial Properties

IRS Guidelines for CIC's

- Specific monies for specific projects;
- Separate bank Account;
- Only "Capital Expenditures";
- No "Maintenance & Operations" expenditures;

Expense Classification

"Capital Expenditures"
Versus
"Maintenance & Operations
Costs"

IRS Guidelines:

• A <u>normal</u>, <u>annual</u> and <u>anticipated</u> expense cannot be a "Capital Expenditure"; it must be considered a "Maintenance Expense".

Cost Threshold Consideration

Established by Policy of the Board of Directors:

Life of 3 yrs or more and Cost more than X




Capital Expenditure

Life of less than 3 yrs and Cost less than X




Maintenance & Operations Cost

Reserve Study Sample





Copyright 2016 Miller Dodson Assoc. Inc.



Cost for typical 1.0 acre pond(5-8' depth), 1,000' shoreline

Cost for typical 1.0 acre pond(5-8' depth), 1,000' shoreline	Pond Service						
\$1,000-\$3,000/year	Water Management-Chemical applications						
\$3,000-\$5,000/year	Water Management-Bacteria applications						
\$200-\$400	10-12" Triploid Grass Carp(20 fish/acre)						
\$200-\$500	Blue Tilapia (200-400 fish/acre)						
\$2,000-\$4,000	Aeration-1 hp aerating fountain						
\$3,000-\$5,000	Aeration-2 diffuser bottom aeration unit						
	Mosquito abatement						
\$1,500-\$2,500/yearly	-chemical						
\$400-\$1,000	-biological (Gambusia, Bluegill, dragonfly, etc.)						
	Dredging-removal of 3' depth-est. 4800 cubic yd						
\$200,000-\$400,000	-hydraulic dredging						
\$100,000-\$300,000	-heavy equipment dredging						
\$50,000-\$70,000	-hauling						
	Upland Shoreline restoration						
\$5,000-\$10,000	-upland planted shoreline						
\$5,000-\$10,000	-regrade and hydroseed						
\$15,000-\$25,000	-reinforced shoreline (turf reinforcement)						

Cost for typical 1.0 acre pond(5-8' depth), 1,000' shoreline (cont.)

	Upland Shoreline restoration
\$5,000-\$10,000	-upland planted shoreline
\$5,000-\$10,000	-regrade and hydroseed
\$15,000-\$25,000	-reinforced shoreline (turf reinforcement)
	Lower Shoreline restoration
\$10,000-\$20,000	-reinforced aquatic planting-coir log and wetland carpet
\$3,000-\$5,000	-Bare root aquatic planting
\$500,000-\$1,000,000	-stonework or bulkhead
\$70,000-\$130,000	-rip-rap
\$500-\$5,000	Engineering consultation
	Storm water feature repairs
\$400-\$1,500	Trash grates and outfall covers
\$7,000-\$13,000	Inflow rip-rap repairs (estimate 50')
\$2,000-\$5,000	Clogged pipe cleaning-Vacuum truck
\$500-\$1,000	Trash and minor debris removal
\$2,000-\$5,000	Vegetation and Debris removal
\$5,000-\$10,000	Tree and branch removal

	COMPONENTS						
PROJE	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NORMAL ECONOMIC LIFE (YRS)	FEMAINING ECONOMIC LIFE (YRS)	PEPLACEMEN COST (I
1	Pond Dredging, hydraulic	acre	3	\$300,000.00	10	5	\$780,000
2	Spoils Hauling & Disposal	acre	3	\$60,000.00	10	5	\$156,00
3	Bog Dredging, mechanical	acre	0	\$200,000.00	50	none	\$30,00
4	Bog Spoils Hauling & Disposal	acre	0	\$60,000.00	50	none	\$9,00
5	Aerating Fountain	each	1	\$20,000.00	14	7	\$20,00
6	Fountain Pump & Motor, 20 hp	each	1	\$8,500.00	14	none	\$8,50
7	Rip-rap major repair	If	50	\$10,000.00	5	3	\$500,00
8	Outfall Structure repair, allowance	Is	1	\$25,000.00	5	5	\$25,00
9	Bank Stabilization, allowance	Is	1	\$10,000.00	5	none	\$10,00
	Shoreline Reinforcement	Is	1				EXCLUDE
	Tree Branch Removal	Is	1				EXCLUDE
	Clogged Inlet & Outflow Pipes	Is	1				EXCLUDE
	Engineering Consultation	Is	1				EXCLUDE
	Inspections	ls	1				EXCLUDE
		SITE	COMPONE	NTS - Replacem	ent Costs	Subtotal	\$1,538,50

Inspections Is 1 EXCLUDED

SITE COMPONENTS - Replacement Costs - Subtotal \$


\$1,538,500


SITE COMPONENTS

COMMENTS

- Pond surface area is approximately 2.6 acres. Assume 1/3 cubic yards of spoils per square yard of surface pending bathymetric study.
- Bog surface is approximately .15 acre. Assume 2/3 cubic yards of spoil per square yard of surface area. NOTE: This will
 not be a re-occurring expense.
- NOTE: Only "Capital Expenditures" allowed in a CIC Reserve Study.
- Maintenance and Operations" expenses are not allowed in CIC Reserve Study.
- Excluded items are examples of "Maintennance and/or Operations" expenses.

	PR	OJECTE	REPL	ACEMENTS - YEA	RS ONE	TO F	TANA AROSO	TTC POND17
item 3 4	2017 - STUDY YEAR Bog Dredging, mechanical Bog Spoils Hauling & Dispos	\$ \$30,000 \$9,000	Item	2018 - YEAR 2	\$	Item	2019 - YEAR 3	ş
6 9	Fountain Pump & Motor, 20 Bank Stabilization, allowanc	\$8,500 \$10,000						
Tot	al Scheduled Replacements	\$57,500	No	Scheduled Replacements		N	o Scheduled Replacements	
Item 7	2020 - YEAR 4 Rip-rap major repair	\$500,000	Item	2021 - YEAR 5	\$	Item 1	2022 - YEAR 6 Pond Dredging, hydraulic	\$ \$780,000
	rup rap major repair	4500,000				2	Spoils Hauling & Disposal	\$156,000
						9	Outfall Structure repair, allow Bank Stabilization, allowanc	\$25,000 \$10,000
Tot	al Scheduled Replacements	\$500,000	No	Scheduled Replacements		Tota	al Scheduled Replacements	\$971,000
item	2023 - YEAR 7	\$	Item	2024 - YEAR 8	\$	Item	2025 - YEAR 9	\$
			5 A	erating Fountain	\$20,000	7	Rip-rap major repair	\$500,000
N	io Scheduled Replacements		Total	Scheduled Replacements	\$20,000	Total	al Scheduled Replacements	\$500,000





The Current Funding Objective as calculated by the Component Method (Fully Funded) is \$540,471 making the reserve account 0.0% funded. See the Appendix for more information on this method.

Facility is located in North Charleston, SC on SE corner of Rivers Avenue and State Road 10-1116.

Year	2017	2018	2019	2020	2021	1st Peak - 2022	2023	2024	2025	2026
Starting Balance Projected Replacements Annual Deposit	(\$57,500) \$288,083	\$288,583	\$288,083	(\$500,000) \$250,003	\$288,883	(\$971,000) \$298,063	\$283,450	(\$20,000) \$283,450	(\$500,000) \$203,450	\$283,450
End of Year Balance	\$230,583	\$518,687	\$898,750	\$594,833	\$892,917	\$200,000	\$483,450	\$596,900	\$290,358	\$483,800
Cumulative Expenditures Cumulative Receipts	\$57,500 \$200,003	\$57,500 \$578,167	\$57,500 \$884,250	\$557,500 \$1,152,333	\$557,500 \$1,440,417	\$1,529,500 \$1,729,500	\$1,528,500 \$1,931,950	\$1,548,500 \$2,135,400	\$2,048,588 \$2,338,850	\$2,048,500 \$2,542,300
Year	2027	2028	2029	2030		2nd Peak - 2032	2033	2034	2035	2036
Projected Replacements Annual Deposit	(\$35,000) \$203,450	\$203,450	\$203,450	(\$500,000) \$203,450	(\$8,500) \$283,450	(\$971,000) \$203,450	\$203,025	\$203,025	(\$500,000) \$200,025	\$203,025
End of Year Balance	\$662,250	\$865,700	\$1,059,150	\$772,600	\$987,550	\$200,000	\$403,025	\$606,060	\$309,075	\$512,100
Cumulative Expenditures Cumulative Receipts	(\$2,089,500) \$2,745,760	(\$2,083,500) \$2,949,200	(\$2,083,500) \$3,152,650	(\$2,563,500) \$3,356,100	(\$2,592,000) \$3,559,550	(\$3,583,000) \$3,783,000	(\$3,583,000) \$3,986,025	(\$3,583,000) \$4,189,060	(\$4,063,000) \$4,372,675	(\$4,083,000 \$4,575,100
Year Projected Replacements Annual Deposit End of Year Balance	2637 (\$35,000) \$209,025 \$690,125	2038 (\$20,800) \$203,825 \$863,150	2039 \$283,025 \$1,050,175	2540 (\$500,800) \$203,025 \$760,200	2041 \$283,825 \$872,225	2042 (\$971,000) \$203,025 \$204,250	2643 \$283,826 \$487,275	\$283,005 \$618,300	2545 (\$508,510) \$209,025 \$364,825	2046 \$283,825 \$587,850
Cumulative Expenditures	(\$4,098,000)	(84,118,000)	(\$4,118,000)	\$750,200 (\$4,618,000)	(\$4,818,000)	(\$5,589,000)	(\$5,589,000)	(\$5.589,000)	(\$6.097,500)	(\$8.087,500
Cumulative Receipts	\$4,778,125	\$4,981,150	\$5,184,175	\$5,387,200	\$5,590,225	\$5,793,250	\$5,986,275	\$5,199,300	\$6,402,325	\$6,605,350
Year	2047	2040	2049	2050	2051	3rd Peak - 2052	2053	2054 4	th Peak - 2055	2066
Projected Replacements Annual Deposit	(\$35,000) \$203,025	\$203,025	\$203,025	(\$500,000) \$203,025	\$203,025	\$203,025	\$166,867	\$166,667	(\$500,000) \$166,667	
End of Year Balance	\$675,875	\$878,900	\$1,081,925	\$784,850	\$987,875	\$200,000	\$366,667	\$533,333	\$200,000	\$200,000
Cumulative Expenditures	(\$8,132,500)	(\$6,132,500)	(\$8,132,600)	(\$8,632,500)	(\$8,632,500)	(\$7,623,500)	(\$7,623,500)	(\$7,623,500)	(\$8,123,600)	(\$9,123,600
Cumulative Receipts	\$8,608,375	\$7,011,480	\$7,214,425	\$7,417,450	\$7,620,475	\$7,823,500	\$7,990,187	\$8,156,833	\$8,323,500	\$8,323,500

EXECUTIVE SUMMARY

The TTC Pond Replacement Reserve Analysis uses the Cash Flow Method (CFM) to calculate Replacement Reserve funding for the periodic replacement of the 9 Projected Replacements identified in the Replacement Reserve Inventory.

\$288,083

RECOMMENDED REPLACEMENT RESERVE FUNDING FOR THE STUDY YEAR, 2017

\$24,006.94 Per unit (average), minimum monthly funding of Replacement Reserves

We recommend the Association adopt a Replacement Reserve Funding Plan based on the annual funding recommendation above. Inflation adjusted funding for subsequent years is shown on Page A5.

TTC Pond reports a that the Association is currently not funding Replacement Reserves.

This Study contains the information necessary for the Association to develop a Funding Plan to address the \$8,123,500 of Projected Replacements identified in the Replacement Reserve Inventory over the 40-year Study Period.

Questions

Copyright 2016 Miller Dodson Assoc. Inc.